WORK AUTHORIZATION

WA 004

(DOT) VOLPE

AUTHORIZATION IS GIVEN TO INITIATE WORK AS DESCRIBED IN THE U.S. DEPARTMENT OF TRANSPORTATION (VOLPE CENTER)- TECHNICAL ASSISTANCE IAG #DW6995388401 AND AS AMENDED. THIS INFORMATION IS PROVIDED FOR COST TRACKING PURPOSES.

SDMS Document ID

2009697

To Be Filled Out by the Remedial Project Manager:

Brief Description of Work to Be Done: SEE ATTACHED

From: June 15, 2003

Site Name: LIBBY ASBESTOS SUPERFUND SITE

EPA Site Id# 08BCRV00

Period of Performance:

Remedial Project Manager: Jim Christiansen

Dollar Amount Needed: \$156,133.00

To: August 15, 2003

To Be Filled Out by the IAG Project Officer:

Previous Amount: \$ -0-

Total Amount to Date: \$156,133.00

DCN: LRV 015 03 T 8ALOE 50102D 08BCRV00 CO01

IAG NUMBER

SUPERFUND ACCOUNT

OBJECT COST

CLASS ORG

AMOUNT

Deob. Fm:

Oblig. To: **DW6995388401**

LRV 015 03 T 8ALOE 50102D 08BCRV00 2507

CO01

\$156,133.00

REMBDIAL PROJECT MANAGER

Date

ORIGINAL TO:

JEFF MARSALA, CINCINNATI FINANCIAL MGMT. CTR.

COPIES TO:

CAROL O'DONNELL, USEPA GRANTS SPECIALIST JOHN McGUIGGEN, VOLPE PROJECT MANAGER JEM CHRISTIANSEN, USEPA PROJECT OFFICER

AUDREY HENKEL, USEPA COST RECOVERY

JUDITH POWELL, PROJECT OFFICER



Background:

As part of their support to the Libby Asbestos Project, the Volpe Center manages and conducts cleanup and remediation tasks, including "cradle-to-grave" hazardous waste management of vermiculate-contaminated insulation (VCI), other asbestos-contaminated material (ACM), and other commingled or associated materials.

Tasks to be Performed:

The Volpe Center shall provide the personnel, materials and supplies to conduct the following tasks:

Task 1. Planning. Conduct activities such as pre-cleanup site walks and investigations, to support planning for cleanup.

Task 2. Cleanup Management and Acquisition Support.

- a. Conduct daily management activities for cleanup activities. Typical tasks include:
 - 1. Monitoring construction schedules, budgets, and plans
 - 2. Approvals and revisions
 - 3. Reporting
 - 4. Health and safety monitoring
 - 5. Inspection, resolution of discrepancies ("punch list"), and acceptance
- b. Conduct acquisition tasks as necessary to support cleanup activities. Tasks include the full scope of pre-award and post-award acquisition and contract management responsibilities.
- Task 3. Cleanup Coordination. Coordinate, as required, with other EPA contractors conducting cleanup activities in Libby.
- Task 4. Reporting. Provide bi-weekly progress updates to the EPA Region 8 Remedial Program Manager. All other reporting will be consistent with the requirements of the Interagency Agreement.
- Task 5. Waste Management. Hazardous waste operations and management of vermiculate-contaminated insulation (VCI), other asbestos-contaminated material (ACM), and other commingled or associated materials.

WAF 4 - Cleanup/Remediation Support (Cleanup)

Cost Estimate

The estimated cost for conducting these tasks is provided on the coversheet for WAF 4.

Period of Performance

The period of performance for conducting these tasks will be 60 calendar days from the date of agreement. The specific dates are provided on the coversheet for WAF 4.

Concurrence:

EPA Region 8 and the Volpe Center have discussed this statement of work and mutually agree to its requirements, the estimated cost, and the schedule.

EPA Region 8 Remedial Program Manager

Date GUUS

Volpe Center Project Manager:

Date

6/4/03

John McGuiggin